
MT455X, MT456X MT465X, MT466X

SUPPLY COVER SLEEVE WITH & WITHOUT BRAIDED SUPPLY LINE




SPECIFICATION SHEET

FLEXIBLE SUPPLY COVER SLEEVE



S.S. BRAIDED SUPPLY LINE



PART NO.	SUPPLY COVER SLEEVE DIM A	BRAIDED SUPPLY LINE <i>DIM B</i>	BRAIDED SUPPLY LINE FITTING 1	BRAIDED SUPPLY LINE FITTING 2
MT455X	11" -13"	NOT INCLUDED	-	-
MT456X	19"-21"	NOT INCLUDED	-	-
MT465X	11"-13"	12" TOILET	3/8" O.D. COMP	7/8" BALLCOCK
MT466X	19"-21"	20" LAVATORY	3/8" O.D. COMP	1/2" FPT

- SUPPLY COVER SLEEVE IS FULLY PLATED
- SUPPLY COVER SLEEVE SLIDES OVER BRAIDED SUPPLY LINE
- ADJUSTABLE END CAPS ALLOW FOR CUSTOM FIT

WARRANTY

FOR WARRANTY INFO PLEASE VISIT WWW.MOUNTAINPLUMBING.COM/PAGE/RESOURCES/WARRANTY

FINISH CARE & MAINTENANCE

NEVER USE ANY HARSH ALKALI, ACID BASED DETERGENTS OR CLEANERS SUCH AS SOFT SCRUB®, SCRUBBING BUBBLES® OR COMET® TO CLEAN. DO NOT USE BRILLO® OR SCOTCH BRITE® PADS. THESE WILL ALL HARM THE FINISH. TO CLEAN, USE ONLY A DAMP SOFT CLOTH AND WIPE GENTLY. STANDARD WINDEX® CAN ALSO BE USED SPARINGLY. IT IS NOT NECESSARY TO WIPE HARD TO REMOVE SPOTS. TO MAINTAIN THE FINISH, WIPE WITH A SOFT DRY CLOTH AFTER USE. AN OCCASIONAL COAT OF PURE CARNAUBA WAX WITHOUT CLEANERS WILL HELP PORTECT THE FINISH.